

**Subject:** 20140609-QHM Portsmouth NAVWARN 35/14 - W Princessa Topmark Missing  
**From:** "NAVY NBCP-COB QHM DEPUTY (Randall, Nicolas Mr)" <NAVYNBCP-COBQHMDEPUTY@mod.uk>  
**Date:** 09/06/2014 09:31  
**To:** "NAVY NBCP-COB QHM DEPUTY (Randall, Nicolas Mr)" <NAVYNBCP-COBQHMDEPUTY@mod.uk>

QUEEN'S HARBOUR MASTER PORTSMOUTH  
NAVIGATION WARNINGS  
No 34/14  
WEST PRINCESSA BUOY TOPMARK MISSING

1. THE WEST PRINCESSA WEST CARDINAL BUOY (50 40.156N 001 03.653W) IS MISSING ITS TOPMARK.
2. VESSELS SHOULD NAVIGATE WITH CAUTION IN THE VICINITY.
3. THE FOLLOWING PORTSMOUTH NAVWARNS REMAIN IN FORCE: 33/14, 27/14, 21/14, 67/13, 65/13, 62/13, 39/13, 29/13, 57/12, 52/11, 40/11, 45/10, 78/05, 10/04.

Sat 7th Jun 2014  
Semaphore Tower  
HM Naval Base, Portsmouth.

Queen's Harbour Master

**N J Randall**  
**Deputy Queen's Harbour Master**  
**Room 402, Semaphore Tower, HM Naval Base, Portsmouth, PO1 3LT**  
Mil: 9380 20189    Civ: 02392 720189  
E-Mail: [NAVYNBCP-COBQHMDEPUTY@mod.uk](mailto:NAVYNBCP-COBQHMDEPUTY@mod.uk)